CREW: 192 WORK ORDER TYPE: MODIFICATIONS			02-60456-68	ISSUE DATE 01/06/11	Page 1 Of 1			
Originator : KENNETH NIELSON	Schedule Date :			Date Completed:		Failure Code:		
Planner : JIMMIE KNAPP		3A						
Drawing No : 2SGB-M2064A		NO		Completed By :		Signature :		
Equip No/Cat: 2SGB0 0	Tag Request :							
Project ID :	Text ID :			Accepted By :		Signature :		
Shutdown : U Unit			CHEDULED					
Ref No :	Last Reading :	No Re	ading				les Legend **	
					W=Whse		ag TL=Tool	P=Plan
7.3. 7		n. n.	0-5 1441-11	To formation		ecord Time Dai		Delays
Step Job Scope		אם או	Safety and Additional		Emp No	Date	Hours	Code/Hrs
		1 1						
1 Install OFA thermocouples and junction boxes for transmation end on OFA system.		1 1	SAFETY / ENVIRONMENTAL					
4 per side on alternating ports with T/C			A. BE AWARE OF OTHER		*****			
installed on top, forward position on			PROGRESS IN THIS AREA					
individual port walls.			*********				• • • • • • • • • • • • • • • • • • • •	
***************	*****		ADDITIONAL INFORMATION	N :				
JOB SCOPE:			a. NONE.	•••				
1. SEE KEN NIELSON FOR PART	TS AND LOCATION		a					
THE NEED TO BE INSTALLED.								
2. INSTALL THE THERMOCOUPLI	ES.							

					*	* IMPORTANT NO	TICE **	
						PONSIBLE FOR		Y AND MUST
						THE REQUIRED		
					JOB YOU ARE	DOING. IF YO	U HAVE ANY QU	JESTIONS
						THE WORK RULES		

Job Feedback/Historical Notes:



REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

IP7_037476